Form Summary

Job Number:	Salem Ridge B
Incident Classification:	Unknown
Incident Report Submitted By:	Buddy Swing
Verita Location	N/A
Incident Type:	Utility Strike
Verita or Sub-Contractor?	Verita
Sub-Contractor:	
Date of Incident:	01/19/2023
Time of Incident:	10:00 AM
Address	Maple Run Dr. Randleman NC 27317
Coordinates:	35.875216, -79.797349
At Fault Utility Strike?	No
Was Utility Located?	Yes
Utility Locate #(1):	C230170535
Utility Locate #(2):	
Utility Locate #(3):	
Utility Type:	Cable/Internet
Utility Depth:	1'
Utility Size:	625 COAX
Utility Owner:	Spectrum
Was the Utility Notified?	Yes
Did the Utility Respond to the Scene?	N/A

Form Summary

Utility Contact:spectrumUtility Contact Phone Number:833-267-6094Utility Contact Email Address:help@charter.comHow Many Customers out of Service?4Incident Description:In-house drill crew struck a 625 coax cable at 1 ft deep performing a tie-in conduit installation. Damage occured 4ft off locate marks. 24" to EOP. Hit happened during use of mini-excavatorWhat was Damaged?spectrumDescribe Damage:In house hit coax using a mini excavator to perform a tie-inWhat has/will be done to prevent future incidents from occuring?NoWas a post accident drug test conducted?NoWas Disciplinary Action Administered?PendingJSAIMG_20230123_123034684.jpg	
Utility Contact Email Address:help@charter.comHow Many Customers out of Service?4Incident Description:In-house drill crew struck a 625 coax cable at 1 ft deep performing a tie-in or conduit installation. Damage occured 4ft off locate marks. 24" to EOP. Hit is happened during use of mini-excavatorWhat was Damaged?spectrumDescribe Damage:In house hit coax using a mini excavator to perform a tie-in circumstances moving forward. Along with being spotted every 50-75 ft.Was a post accident drug test conducted?NoWas JSA completed?Yes (Upload JSA Below)Was Disciplinary Action Administered?PendingJSAIM6_20230123_123034684.jpg	
How Many Customers out of Service?4Incident Description:In-house drill crew struck a 625 coax cable at 1 ft deep performing a tie-in conduit installation. Damage occured 4ft off locate marks. 24" to EOP. Hit happened during use of mini-excavatorWhat was Damaged?spectrumDescribe Damage:In house hit coax using a mini excavator to perform a tie-inWhat has/will be done to prevent future incidents from occuring?No more digging within the 2 ft mark of locates. Needs to be hand dug in th circumstances moving forward. Along with being spotted every 50-75 ft.Was a post accident drug test conducted?NoWas Disciplinary Action Administered?PendingJSAIMG_20230123_123034684.jpg	
Incident Description:In-house drill crew struck a 625 coax cable at 1 ft deep performing a tie-in or conduit installation. Damage occured 4ft off locate marks. 24" to EOP. Hit happened during use of mini-excavatorWhat was Damaged?spectrumDescribe Damage:In house hit coax using a mini excavator to perform a tie-in circumstances moving forward. Along with being spotted every 50-75 ft.Was a post accident drug test conducted?NoWas JSA completed?Yes (Upload JSA Below)Was Disciplinary Action Administered?PendingJSAIMG_20230123_123034684.jpg	
conduit installation. Damage occured 4ft off locate marks. 24" to EOP. Hit happened during use of mini-excavatorWhat was Damaged?spectrumDescribe Damage:In house hit coax using a mini excavator to perform a tie-inWhat has/will be done to prevent future incidents from occuring?No more digging within the 2 ft mark of locates. Needs to be hand dug in th circumstances moving forward. Along with being spotted every 50-75 ft.Was a post accident drug test conducted?NoWas JSA completed?Yes (Upload JSA Below)Was Disciplinary Action Administered?PendingIMG_20230123_123034684.jpg	
Describe Damage:In house hit coax using a mini excavator to perform a tie-inWhat has/will be done to prevent future incidents from occuring?No more digging within the 2 ft mark of locates. Needs to be hand dug in th circumstances moving forward. Along with being spotted every 50-75 ft.Was a post accident drug test conducted?NoWas JSA completed?Yes (Upload JSA Below)Was Disciplinary Action Administered?PendingJSAIMG_20230123_123034684.jpg)Se
What has/will be done to prevent future incidents from occuring?No more digging within the 2 ft mark of locates. Needs to be hand dug in th circumstances moving forward. Along with being spotted every 50-75 ft.Was a post accident drug test conducted?NoWas JSA completed?Yes (Upload JSA Below)Was Disciplinary Action Administered?PendingJSAIMG_20230123_123034684.jpg)Se
incidents from occuring?circumstances moving forward. Along with being spotted every 50-75 ft.Was a post accident drug test conducted?NoWas JSA completed?Yes (Upload JSA Below)Was Disciplinary Action Administered?PendingJSAIMG_20230123_123034684.jpg	ese
Was JSA completed?Yes (Upload JSA Below)Was Disciplinary Action Administered?PendingJSAIMG_20230123_123034684.jpg	
Was Disciplinary Action Administered? Pending JSA IMG_20230123_123034684.jpg	
JSA IMG_20230123_123034684.jpg	
Picture of System Man	
Picture of Dig Ticket IMG_20230123_124700447.jpg	
System Map Title Block	
Image upload 1 IMG_20230123_123034684.jpg	
Description of Image 1 Damage	
Image upload 2	
Description of Image 2 Damage	
Image upload 3	
Description of Image 3	
Image upload 4	

Form Summary	
Image upload 5	
Description of Image 5	
Image upload 6	
Description of Image 6	
Image upload 7	
Description of Image 7	
Image upload 8	
Description of Image 8	
Incident Reported By:	Randy Beal
Job Title:	Construction Manager
Email address:	Rbeal@veritacorp.com
Phone number	336-470-8866
Date:	01/23/2023
Signature:	RB

The message has been sent from 24.88.160.7 us at 2023-01-23 on Chrome 109.0.0.0 Entry ID: 7 Referrer: https://www.veritanet.com/ Form Host: https://www.veritanet.com/safety