



INCIDENT/INJURY REPORT

Incident Type:* Verita Location* Incident Date:* Time of Incident:* Date Reported:*

EMPLOYEE INFORMATION

Employee Name:* Employee Phone Number:*

Employee Address:

Employee Email Address: Job Title:* Date of Hire:

INCIDENT DETAILS

Crew Size: Crew Foreman/Supervisor:*

Incident Location:*

Location on Google map



Description of Incident: *Please describe in detail what happened**

On 02/01/22 our mechanic noticed new damage to the rear bumper of 1720. I spoke to Jose and Roy and they stated they had no knowledge of how it happened. On 02/01/22 and 02/02/22 Their vehicle inspection said nothing about the damage.

Describe any Unsafe Procedures or Equipment Failures which may have Contributed to the Incident:*

Unknown

What Has/Will be done to Prevent Similar Incidents from Occuring?*

They said they will be more diligent with their vehicle inspections. I have noticed when they do an inspection they are sitting in the truck and not doing a walk around.

ADDITIONAL PHOTOS AND DOCUMENTS

File / Image upload

202302... (1 MB)



File / Image upload

202302... (898 KB)



File / Image upload

Driver_... (274 KB)



File / Image upload

Forman... (271 KB)



File / Image upload

Vehicle_... (742 KB)



File / Image upload

Vehicle_... (169 KB)



File / Image upload

Choose files or drag here

File / Image upload

Choose files or drag here

SUBMISSION

Report Completed By:*

Dan

Job Title:*

Cooper

Safety Specialist

Phone number:*

616 250 7006


Email address:*

dcooper@veritacorp.com

Signature:*

Date:*

Sign here

A handwritten signature in black ink, appearing to be 'D. L.', written on a horizontal line. The signature is positioned to the right of the 'Sign here' text. A small grey square icon with a white dot is located at the end of the signature.

02/06/2023

