

## Form Summary

<b>Job Number:</b>	Salem Ridge B
<b>Incident Classification:</b>	General Liability
<b>Incident Report Submitted By:</b>	Cody Cook
<b>Verita Location</b>	North Carolina
<b>Incident Type:</b>	Utility Strike
<b>Verita or Sub-Contractor?</b>	Verita
<b>Sub-Contractor:</b>	
<b>Date of Incident:</b>	02/01/2023
<b>Time of Incident:</b>	03:30 PM
<b>Address</b>	Red Cedar Ct & Big Oak Way Randleman North Carolina 27317
<b>Coordinates:</b>	
<b>At Fault Utility Strike?</b>	No
<b>Was Utility Located?</b>	Yes
<b>Utility Locate #(1):</b>	
<b>Utility Locate #(2):</b>	
<b>Utility Locate #(3):</b>	
<b>Utility Type:</b>	Electric
<b>Utility Depth:</b>	3'5"
<b>Utility Size:</b>	Primary
<b>Utility Owner:</b>	Duke Energy
<b>Was the Utility Notified?</b>	Yes
<b>Did the Utility Respond to the Scene?</b>	Yes

## Form Summary

### Utility Contact:

Utility Contact Phone Number: 800-769-3766

### Utility Contact Email Address:

How Many Customers out of Service? Whole neighborhood

**Incident Description:** Crew tried spotting primary power line and could not get it spotted. They ended up digging a 6' wide window 4' deep. This gave them their 2' tolerance on each side of the marks plus an additional 1'. Given the all clear to come through the hole and came in at 3'3". Shortly thereafter, a homeowner came out and said they were out of power. Strike alert never went off on drill. Power company was then notified and responded to the scene shortly after, de energizing line. Rods were pulled back and as of now deemed not at fault.

**What was Damaged?** Primary power

**Describe Damage:** Primary power line feeding sub division

**What has/will be done to prevent future incidents from occurring?** In the future when dealing with life threatening utilities, a window is not good enough. We need to exhaust every effort in spotting these types of utilities moving forward. Call in 3 hr retransmit, call power company as well. Even though we may not be liable for the damage, it saves a lot of headache and can potentially save a life when taking this extra effort.

**Was a post accident drug test conducted?** No

**Was JSA completed?** Yes (Upload JSA Below)

**Was Disciplinary Action Administered?** Pending

**JSA** [Red\\_Cedar\\_&\\_Big\\_Oak\\_JSA\\_1.jpg](#)

**Picture of System Map** [Red\\_Cedar\\_&\\_Big\\_Oak\\_JSA\\_2.jpg](#)

**Picture of Dig Ticket**

**System Map Title Block**

**Image upload 1** [Red\\_Cedar\\_&\\_Big\\_Oak\\_Power\\_1.jpg](#)

**Description of Image 1**

**Image upload 2** [Red\\_Cedar\\_&\\_Big\\_Oak\\_Power\\_2.jpg](#)

**Description of Image 2**

**Image upload 3** [Red\\_Cedar\\_&\\_Big\\_Oak\\_Power\\_3.jpg](#)

## Form Summary

Description of Image 3

Image upload 4

[Red\\_Cedar\\_&\\_Big\\_Oak\\_Power\\_4.jpg](#)

Description of Image 4

Image upload 5

[Red\\_Cedar\\_&\\_Big\\_Oak\\_Power\\_5.jpg](#)

Description of Image 5

Image upload 6

[Red\\_Cedar\\_&\\_Blg\\_Oak\\_Power\\_6.jpg](#)

Description of Image 6

Image upload 7

Description of Image 7

Image upload 8

Description of Image 8

Incident Reported By:

Cody Cook

Job Title:

Construction Manager

Email address:

ccook@veritacorp.com

Phone number

734-536-4996

Date:

02/02/2023

Signature:



The message has been sent from 24.88.160.7 us at 2023-02-02 on Chrome 109.0.0.0

Entry ID: 14

Referrer: (no referrer)

Form Host: <https://www.veritanet.com/safety>