

Form Summary

Job Number:	SOF-31003/IMP23130
Incident Classification:	General Liability
Incident Report Submitted By:	Jason Riley
Verita Location	Northville
Incident Type:	Utility Strike
Verita or Sub-Contractor?	Verita
Sub-Contractor:	
Date of Incident:	02/07/2023
Time of Incident:	02:07 PM
Address	6400 East Michigan 36 Whitmore Lake Michigan 48139
Coordinates:	
At Fault Utility Strike?	No
Was Utility Located?	No
Utility Locate #(1):	2023020101896
Utility Locate #(2):	
Utility Locate #(3):	
Utility Type:	Water
Utility Depth:	Approx 3' to 3'8"
Utility Size:	Unknown
Utility Owner:	Hamburg Twp DPW
Was the Utility Notified?	Yes
Did the Utility Respond to the Scene?	Yes

Form Summary

Utility Contact:

Utility Contact Phone Number:

Utility Contact Email Address:

How Many Customers out of Service? Unkown

Incident Description: When crew arrived on site they called in an incomplete staking/unmarked. Positive response said we were either cleared or marked on all utilities. Once they were cleared by USIC to drill they started to drill. While drilling 6' off the gas marks around 3' - 3'8" towards the end of the bore shot they noticed water flowing out of the ground about half way between the drill and the drill head. Person working at the treatment plant turned water off and said they will dig it up in the morning to fix. Agreed we were not at fault. But I wasn't there to verify that statement. The line we hit was an unmarked service line headed southwest across nagel street to an out building.

What was Damaged? Water service line

Describe Damage: Unkown since they're waiting until tomorrow to dig up and repair.

What has/will be done to prevent future incidents from occurring? USIC could do a better job marking all utilities

Was a post accident drug test conducted? No

Was JSA completed? Yes (Upload JSA Below)

Was Disciplinary Action Administered? No

JSA

Picture of System Map [DE9205FD-FA8C-4564-ADFD-69FAEFF01E66.jpeg](#)

Picture of Dig Ticket

System Map Title Block

Image upload 1 [B3C740F7-1A9E-4375-B550-D4740B8F7E42.jpeg](#)

Description of Image 1

Image upload 2 [EA63332A-D404-45B5-8F90-34E90D3291C7.jpeg](#)

Description of Image 2

Image upload 3 [EF4778AD-B815-4F0C-8AEB-7D9B01778DDB.jpeg](#)

Form Summary

Description of Image 3

Image upload 4

[4F11E39C-1F61-418B-B004-CEFC8808EEC0.jpeg](#)

Description of Image 4

Image upload 5

Description of Image 5

Image upload 6

Description of Image 6

Image upload 7

Description of Image 7

Image upload 8

Description of Image 8

Incident Reported By:

Jason Riley

Job Title:

Safety Specialist

Email address:

jriley@veritacorp.com

Phone number

734-286-4177

Date:

02/07/2023

Signature:



The message has been sent from 174.240.151.159 us at 2023-02-07 on Safari 15.6.1
Entry ID: 18
Referrer: (no referrer)
Form Host: <https://www.veritanet.com/safety>