

Form Summary

Job Number:	0001216298
Incident Classification:	General Liability
Incident Report Submitted By:	Jason Riley
Verita Location	Northville
Incident Type:	Utility Strike
Verita or Sub-Contractor?	Verita
Sub-Contractor:	
Date of Incident:	01/30/2023
Time of Incident:	11:20 AM
Address	2411 Oak Valley Dr Ann Arbor Michigan 48103
Coordinates:	
At Fault Utility Strike?	No
Was Utility Located?	No
Utility Locate #(1):	2023010501457
Utility Locate #(2):	
Utility Locate #(3):	
Utility Type:	Electric
Utility Depth:	36"
Utility Size:	3 phase
Utility Owner:	DTE Energy
Was the Utility Notified?	Yes
Did the Utility Respond to the Scene?	Yes

Form Summary

Utility Contact:

N/a

Utility Contact Phone Number:

180-047-7474

Utility Contact Email Address:

How Many Customers out of Service?

215

Incident Description:

Crew arrived on site at approximately 9:00am. Checked positive response, positive response came back as marked all utilities. Chose a bore path to drill in approximately 8' wide between existing utilities. As they were drilling out approximately 150' the drill head pushed a group of rocks into an unmarked 3 phase DTE primary causing the 3 phase to short out and the drill strike alert to go off. Justin immediately stopped drilling and told the operator to stay put on the drill until DTE arrives. DTE arrived shortly after and de-energized the 3phase and re-routed power to restore service to customers. There was only 1 red DTE flag on site at the end of the shot that the crew was attempting to dig up and spot. The location of the lone flag made it appear as though power was coming from across the street to a transformer.

What was Damaged?

3 phase DTE primary

Describe Damage:

3phase primary shorted out causing an outage of 215 customers.

What has/will be done to prevent future incidents from occurring?

USIC needs to mark everything if positive response says everything is marked

Was a post accident drug test conducted?

No

Was JSA completed?

Yes (Upload JSA Below)

Was Disciplinary Action Administered?

No

JSA

Picture of System Map

[E8B2C4B7-637D-4006-9D4E-AF4D876E5B7E.jpeg](#)

Picture of Dig Ticket

[image.jpg](#)

System Map Title Block

Image upload 1

[842908F0-5E57-4D3E-A305-94E460D9ED6E.jpeg](#)

Description of Image 1

Image upload 2

[1A19080D-1646-44CA-B92D-80798CB62513.jpeg](#)

Description of Image 2

Form Summary

Image upload 3

[3F27E94B-39DA-44E0-88C4-27A2414F9D48.jpeg](#)

Description of Image 3

Image upload 4

[78DD111A-2C09-4161-95C9-D89F92DCEA58.jpeg](#)

Description of Image 4

Image upload 5

Description of Image 5

Image upload 6

Description of Image 6

Image upload 7

Description of Image 7

Image upload 8

Description of Image 8

Incident Reported By:

Jason Riley

Job Title:

Safety Specialist

Email address:

jriley@veritacorp.com

Phone number

734-286-4177

Date:

01/31/2023

Signature:



The message has been sent from 174.240.151.18 zz at 2023-01-31 on Safari 15.6.1

Entry ID: 11

Referrer: (no referrer)

Form Host: <https://www.veritanet.com/safety>