



INCIDENT/INJURY REPORT

Incident Type:*

Verità Location*


Incident Date:*


Time of Incident:*


Date Reported:*

Incident Without... ▾

North Carolina ▾

01/28/2023 

11:30 AM 

01/28/2023 

EMPLOYEE INFORMATION

Employee Name:*

David

Arrasmith

Employee Phone Number:*

910 946 1774

Employee Address:

2406 Farrington Point Dr

Winston Salem

North Carolina ▾

27107


Employee Email Address:

arrasmithdavid@gmail.com

Job Title:*

Foreman

Date of Hire:

12/19/2022 

INCIDENT DETAILS

Crew Size:

2

Crew Foreman/Supervisor:*

David

Arrasmith

Incident Location:*

Niagara Parkway

Niagara Falls

State ▾

27292

Location on Google map



Description of Incident: *Please describe in detail what happened**

On the day before the incident occurred the crew spent all day digging a 10' hole using shoring to protect the trench to retrieve lost tooling underground. They then backfilled the hole to the best of their ability and called it a day before coming out the next day to finish cleaning things up. It had rained quite a bit overnight and naturally it caused the dirt to settle. The foreman, as he was attempting to move the mini to another part of the site, attempted to cross over the hole instead of going around and it immediately sunk. It almost tipped over if it wasn't for tying it off to the truck. A wrecker had to be called in to assist in pulling it out of the mud.

Describe any Unsafe Procedures or Equipment Failures which may have Contributed to the Incident:*

Attempting to drive an excavator across a hole that was dug 10' the day prior without properly backfilling and knowing it had rained overnight

What Has/Will be done to Prevent Similar Incidents from Occuring?*

Coached the foreman on proper backfilling techniques
To be mindful of the area in which you are working and to take into account the ground conditions in which you are dealing with

ADDITIONAL PHOTOS AND DOCUMENTS

File / Image upload

Stuck_... (1.4 MB) ×

File / Image upload

Choose files or drag here

File / Image upload

Choose files or drag here

File / Image upload

Choose files or drag here

File / Image upload

Choose files or drag here

File / Image upload

Choose files or drag here

File / Image upload

Choose files or drag here

File / Image upload

Choose files or drag here

SUBMISSION

Report Completed By:*

Cody

Job Title:*

Cook

Construction Manager

Phone number:*

734 536 4996

Email address:*

ccook@veritacorp.com

Signature:*

Date:*


Sign here

01/31/2023 