

**Incident Detail** Incident Name: 2703 Meadowview Dr. Zeeland Mi. Date of Incident: 01/06/2023 09:00 AM **Incident Type: PROPERTY DAMAGE** Workday Period: During normal work activities **Activity Details:** While pot holing Gas service, line was cut with shovel. Location: South Bend - Front yard of Residence At Fault Utility Strike?: Was JSA posted and properly filled out?: Yes yes Hit-kit pictures inlcuded?: Was employee sent for a drug/alcohol screen?: yes **Utility Locate #?: Verita or Subcontractor Crew?:** 2022122000636 Verita If Subcontractor, please specify name::

# Detail

#### **Status**

Report Only (No Claim Filed)

**Type** 

☐ Building (Exterior) ☐ Building (Interior)

☐ Equipment (Production) ☐ Equipment (Non-Production)

☐ Landscaping ☐ Merchandise/Inventory

☐ Vehicle (Passenger) ☐ Vehicle (Other)

Other

## Describe Incident (how, where, why)

David was potholing the gas service and cut into plastic 1" line.

#### **Describe Extent of damage/loss**

Cut gas line causing it to leak.

### **Person Information**

Name Phone Email Address City State Zip

David Alcantara 765-228-4155 INDIANAPOLIS IN

### **Witness Information**

Name Phone Email Address City State Zip

### **Submission Detail**

**Submitted by:** Jeff Beatty **Date/Time:** 01/06/2023 12:02 PM **Doc ID:** #10663

















