

## Form Summary

<b>Job Number:</b>	Salem Ridge B
<b>Incident Classification:</b>	N/A
<b>Incident Report Submitted By:</b>	Randy Beal
<b>Verita Location</b>	North Carolina
<b>Incident Type:</b>	Utility Strike
<b>Verita or Sub-Contractor?</b>	Verita
<b>Sub-Contractor:</b>	
<b>Date of Incident:</b>	01/23/2023
<b>Time of Incident:</b>	09:30 AM
<b>Address</b>	Maple Run Dr Randleman nc 27317
<b>Coordinates:</b>	35.874628, -79.797384
<b>At Fault Utility Strike?</b>	Yes
<b>Was Utility Located?</b>	Yes
<b>Utility Locate #(1):</b>	C230170535
<b>Utility Locate #(2):</b>	
<b>Utility Locate #(3):</b>	
<b>Utility Type:</b>	Cable/Internet
<b>Utility Depth:</b>	1'
<b>Utility Size:</b>	625 COAX
<b>Utility Owner:</b>	Spectrum
<b>Was the Utility Notified?</b>	N/A
<b>Did the Utility Respond to the Scene?</b>	Yes

## Form Summary

<b>Utility Contact:</b>	spectrum
<b>Utility Contact Phone Number:</b>	855-757-7328
<b>Utility Contact Email Address:</b>	help@charter.com
<b>How Many Customers out of Service?</b>	4
<b>Incident Description:</b>	Mini excavator struck a Spectrum 625 coax within the 2 ft. tolerance.
<b>What was Damaged?</b>	Spectrum 625 coax
<b>Describe Damage:</b>	Utility was struck during the tie-in process of conduit
<b>What has/will be done to prevent future incidents from occurring?</b>	Crew will have to handdig in these areas. If a utility is in question, we have a locator in the truck for these situations.
<b>Was a post accident drug test conducted?</b>	No
<b>Was JSA completed?</b>	Yes (Upload JSA Below)
<b>Was Disciplinary Action Administered?</b>	Pending
<b>JSA</b>	<a href="#">IMG_20230125_092101670.jpg</a>
<b>Picture of System Map</b>	
<b>Picture of Dig Ticket</b>	<a href="#">2_damage.jpg</a>
<b>System Map Title Block</b>	
<b>Image upload 1</b>	
<b>Description of Image 1</b>	
<b>Image upload 2</b>	
<b>Description of Image 2</b>	
<b>Image upload 3</b>	
<b>Description of Image 3</b>	
<b>Image upload 4</b>	
<b>Description of Image 4</b>	
<b>Image upload 5</b>	

## Form Summary

Description of Image 5

Image upload 6

Description of Image 6

Image upload 7

Description of Image 7

Image upload 8

Description of Image 8

**Incident Reported By:** Randy Beal

**Job Title:** Construction Manager

**Email address:** Rbeal@veritacorp.com

**Phone number** 336-470-8866

**Date:** 01/23/2023

**Signature:** 

The message has been sent from 24.88.160.7 us at 2023-01-25 on Chrome 109.0.0.0

Entry ID: 9

Referrer: (no referrer)

Form Host: <https://www.veritanet.com/safety>