

Form Summary

Job Number:	A0225MD
Incident Classification:	General Liability
Incident Report Submitted By:	Daniel Cooper
Verita Location	Grand Rapids
Incident Type:	Utility Strike
Verita or Sub-Contractor?	Verita
Sub-Contractor:	
Date of Incident:	01/10/2023
Time of Incident:	11:00 AM
Address	3258 Michael Ave Wyoming MI 49010
Coordinates:	42.90511753283634, -85.69471277557139
At Fault Utility Strike?	No
Was Utility Located?	Yes
Utility Locate #(1):	202230101918
Utility Locate #(2):	
Utility Locate #(3):	
Utility Type:	
Utility Depth:	36"
Utility Size:	1"
Utility Owner:	Consumers Energy
Was the Utility Notified?	Yes
Did the Utility Respond to the Scene?	Yes

Form Summary

Utility Contact:

Utility Contact Phone Number:

Utility Contact Email Address:

How Many Customers out of Service? unknown

Incident Description: Power locate was 11' off, we hit them while digging with the excavator. It took out power to AT&Ts PFP, they came and hooked a generator up to it until Consumers Energy could fix the wire.

What was Damaged? 1 leg of a three phase wire

Describe Damage: The line was severed

What has/will be done to prevent future incidents from occurring?

Was a post accident drug test conducted? No

Was JSA completed? Yes (Upload JSA Below)

Was Disciplinary Action Administered? No

JSA [DOC011123_01112023100158950.pdf](#)

Picture of System Map [Overview_and_Print.jpg](#)

Picture of Dig Ticket [2023-01-11_10-05-02.jpg](#)

System Map Title Block

Image upload 1 [20230110_152906.jpg](#)

Description of Image 1 hit kit

Image upload 2 [20230110_152848.jpg](#)

Description of Image 2 close up


Image upload 3 [20230110_153929.jpg](#)

Description of Image 3 power locates

Image upload 4 [20230110_151818.jpg](#)

Description of Image 4 damage

Form Summary

Image upload 5	20230110_152931.jpg
Description of Image 5	running line
Image upload 6	Incident_report.pdf
Description of Image 6	incident report
Image upload 7	20230110_153035.jpg
Description of Image 7	Generator
Image upload 8	
Description of Image 8	
Incident Reported By:	Daniel Cooper
Job Title:	Safety Specialist
Email address:	dcooper@veritacorp.com
Phone number	616-250-7006
Date:	01/11/2023
Signature:	

The message has been sent from 47.50.98.142 us at 2023-01-11 on Chrome 108.0.0.0

Entry ID: 4

Referrer: (no referrer)

Form Host: <https://www.veritanet.com/safety>