

Form Summary

Job Number:	Plat 5&6 BC#22CIP-0076
Incident Classification:	General Liability
Incident Report Submitted By:	Kevin J. Klein
Verita Location	Toledo
Incident Type:	Property Damage
Verita or Sub-Contractor?	Verita
Sub-Contractor:	
Date of Incident:	01/26/2023
Time of Incident:	03:33 PM
Address	9225 Village Meadows Temperance MI 48457
Coordinates:	
At Fault Utility Strike?	Yes
Was Utility Located?	Yes
Utility Locate #(1):	2023011302082
Utility Locate #(2):	
Utility Locate #(3):	
Utility Type:	Other
Utility Depth:	2"
Utility Size:	
Utility Owner:	
Was the Utility Notified?	
Did the Utility Respond to the Scene?	

Form Summary

Utility Contact:

Utility Contact Phone Number:

Utility Contact Email Address:

How Many Customers out of Service?

Incident Description: Cut invisible dog fence.

What was Damaged? wire

Describe Damage: Cut the wire while removing sod.

What has/will be done to prevent future incidents from occurring? Impossible to prevent, homeowners don't know where the wire is at 90% of the time.

Was a post accident drug test conducted? No

Was JSA completed? Yes (Upload JSA Below)

Was Disciplinary Action Administered? No

JSA

Picture of System Map

Picture of Dig Ticket

System Map Title Block

Image upload 1

Description of Image 1

Image upload 2

Description of Image 2

Image upload 3

Description of Image 3

Image upload 4

Description of Image 4

Image upload 5

Form Summary

Description of Image 5

Image upload 6

Description of Image 6

Image upload 7

Description of Image 7

Image upload 8

Description of Image 8

Incident Reported By: Kevin J. Klein

Job Title: Field Supervisor

Email address: kklein@veritacorp.com

Phone number 734-634-9086

Date: 02/06/2023

Signature:



The message has been sent from 216.200.93.90 us at 2023-02-06 on Chrome 109.0.0.0

Entry ID: 17

Referrer: (no referrer)

Form Host: <https://www.veritanet.com/safety>