



Incident Detail

| | | | |
|---|--|--|--|
| Incident Name: ATT A028RC7 | | Date of Incident: 01/18/2023 09:32 AM | |
| Incident Type: GENERAL LIABILITY | | | |
| Workday Period: During normal work activities | | Activity Details: Drilling ATT conduit | |
| Location: Indianapolis - 193 innisbrooke dr | | | |
| At Fault Utility Strike? : yes | | Was JSA posted and properly filled out?: yes | |
| Hit-kit pictures included?: yes | | Was employee sent for a drug/alcohol screen?: no | |
| Utility Locate #?: 2301184762 | | Verita or Subcontractor Crew?: Subcontractor | |
| If Subcontractor, please specify name:: Bulleye | | IMP / SOF ?: | |

Detail

Status
Report Only (No Claim Filed)

- Type**
- Bodily Injury/Medical Liability
 - Personal Injury Liability (i.e. libel/slander, copyright infringement)
 - Property Damage Liability
 - Product Liability
 - Professional Liability
 - Environmental/Pollution Liability
 - Cyber Liability
 - Directors/Officers Liability
 - Other

Describe Incident (how, where, why)
Was drilling and hit Comcast cable

Describe Extent of damage/loss
loss of service

Person Information

| Name | Phone | Email | Address | City | State | Zip |
|------|-------|-------|---------|------|-------|-----|
|------|-------|-------|---------|------|-------|-----|

Witness Information

| Name | Phone | Email | Address | City | State | Zip |
|------|-------|-------|---------|------|-------|-----|
|------|-------|-------|---------|------|-------|-----|

Submission Detail

Submitted by: Sylvester Hardrick **Date/Time:** 01/20/2023 09:34 AM **Doc ID:** #10673

Incident Photo(s)

