

Form Summary

Job Number:	JB1018649
Incident Classification:	General Liability
Incident Report Submitted By:	Daniel Cooper
Verita Location	Grand Rapids
Incident Type:	Utility Strike
Verita or Sub-Contractor?	Verita
Sub-Contractor:	
Date of Incident:	01/17/2023
Time of Incident:	01:49 PM
Address	48 Hamilton ST Douglas MI 49406
Coordinates:	42.64587682062336, -86.2101597899478
At Fault Utility Strike?	No
Was Utility Located?	Yes
Utility Locate #(1):	2023011001656
Utility Locate #(2):	
Utility Locate #(3):	
Utility Type:	Electric
Utility Depth:	unknown
Utility Size:	unknown
Utility Owner:	Consumers Energy
Was the Utility Notified?	Yes
Did the Utility Respond to the Scene?	Yes

Form Summary

Utility Contact: Brenda Ezzell

Utility Contact Phone Number: 616-213-5266

Utility Contact Email Address:

How Many Customers out of Service? unknown

Incident Description: While staking the drill the strike alert went off, the operator immediately pulled his stakes out. power was not marked where the damage occurred.

What was Damaged? Primary Line

Describe Damage: unknown

What has/will be done to prevent future incidents from occurring? Nothing, Consumers cleared us of fault and confirmed that the closet mark was 10' from damage. Notification # 1065837579

Was a post accident drug test conducted? No

Was JSA completed? Yes (Upload JSA Below)

Was Disciplinary Action Administered? No

JSA [JSA.pdf](#)

Picture of System Map [print.pdf](#)

Picture of Dig Ticket [locate.jpg](#)

System Map Title Block

Image upload 1 [2023-01-18_11-29-11.jpg](#)

Description of Image 1

Image upload 2 [2023-01-18_11-30-41.jpg](#)

Description of Image 2

Image upload 3 [IMG_0809.jpg](#)

Description of Image 3

Image upload 4 [IMG_0813.jpg](#)

Description of Image 4

Form Summary

Image upload 5

[vmacocss05_1356682994647-1-0.jpg](#)

Description of Image 5

Image upload 6

[vmacocss05_1356685449322-1-0.jpg](#)

Description of Image 6

Image upload 7

Description of Image 7

Image upload 8

Description of Image 8

Incident Reported By:

Daniel Cooper

Job Title:

Safety Specialist

Email address:

dcooper@veritacorp.com

Phone number

616-250-7006

Date:

01/17/2023

Signature:



The message has been sent from 47.50.98.142 us at 2023-01-19 on Chrome 108.0.0.0

Entry ID: 5

Referrer: (no referrer)

Form Host: <https://www.veritanet.com/safety>