



**Incident Detail**

<b>Incident Name:</b> 11610 Lima Rd, Fort Wayne, IN 46818		<b>Date of Incident:</b> 01/11/2023 01:01 PM	
<b>Incident Type:</b> GENERAL LIABILITY			
<b>Workday Period:</b> During normal work activities		<b>Activity Details:</b> crew were in process of setting a vault.	
<b>Location:</b> Fort Wayne - on west side of Lima 500' south of Carroll rd.			
<b>At Fault Utility Strike? :</b> yes		<b>Was JSA posted and properly filled out?:</b> yes	
<b>Hit-kit pictures included?:</b> yes		<b>Was employee sent for a drug/alcohol screen?:</b> no	
<b>Utility Locate #?:</b> 2211212159		<b>Verita or Subcontractor Crew?:</b> Verita	
<b>If Subcontractor, please specify name::</b>		<b>IMP / SOF ?:</b> IMP 21296	

**Detail**

**Status**  
<#IncidentGLStatus#>

- Type**
- Bodily Injury/Medical Liability  Personal Injury Liability (i.e. libel/slander, copyright infringement)
  - Property Damage Liability  Product Liability
  - Professional Liability  Environmental/Pollution Liability
  - Cyber Liability  Directors/Officers Liability
  - Other

**Describe Incident (how, where, why)**  
crew was digging an existing hole deeper to clear water and soil to set a vault. they then snagged an unmarked phone line. turns out 811 tickets for location had expired and were not good at time of dig.

**Describe Extent of damage/loss**  
pending USIC. line is unmarked and existing flags are over 4 feet away from damaged lines.

**Person Information**

Name	Phone	Email	Address	City	State	Zip
------	-------	-------	---------	------	-------	-----

**Witness Information**

Name	Phone	Email	Address	City	State	Zip
------	-------	-------	---------	------	-------	-----

**Submission Detail**

**Submitted by:** David Wilburn **Date/Time:** 01/11/2023 01:03 PM **Doc ID:** #10668

Incident Photo(s)

