Form Summary	
Job Number:	JB0000183744
Incident Classification:	General Liability
Incident Report Submitted By:	Dan Cooper
Verita Location	Grand Rapids
Incident Type:	Utility Strike
Verita or Sub-Contractor?	Verita
Sub-Contractor:	
Date of Incident:	01/31/2023
Time of Incident:	10:00 AM
Address	4065 Plainfeild AveNE Grand Rapids MI 49505
Coordinates:	43.03773650674147, -85.61500297459679
Coordinates: At Fault Utility Strike?	43.03773650674147, -85.61500297459679 Yes
At Fault Utility Strike?	Yes
At Fault Utility Strike? Was Utility Located?	Yes N/A
At Fault Utility Strike? Was Utility Located? Utility Locate #(1):	Yes N/A
At Fault Utility Strike? Was Utility Located? Utility Locate #(1): Utility Locate #(2):	Yes N/A
At Fault Utility Strike? Was Utility Located? Utility Locate #(1): Utility Locate #(2): Utility Locate #(3):	Yes N/A NA
At Fault Utility Strike? Was Utility Located? Utility Locate #(1): Utility Locate #(2): Utility Locate #(3): Utility Type:	Yes N/A NA Telecom
At Fault Utility Strike? Was Utility Located? Utility Locate #(1): Utility Locate #(2): Utility Locate #(3): Utility Type: Utility Depth:	Yes N/A NA Telecom NA -aerial
At Fault Utility Strike? Was Utility Located? Utility Locate #(1): Utility Locate #(2): Utility Locate #(3): Utility Type: Utility Depth: Utility Size:	Yes N/A NA Telecom NA -aerial 864 Fibers

No

Did the Utility Respond to the Scene?

Form Summary	
Utility Contact:	Chris Lentini
Utility Contact Phone Number:	616-204-2152
Utility Contact Email Address:	
How Many Customers out of Service?	Unknown
Incident Description:	A 864 fiber optic cable was accidently cut. The employee mistook it for a 875 coax cable.
What was Damaged?	a 864 fiber cable
Describe Damage:	Cable was cut all the way through.
What has/will be done to prevent future incidents from occuring?	The tech said he would triple check before cutting in the future.
Was a post accident drug test conducted?	No
Was JSA completed?	No
Was Disciplinary Action Administered?	No
JSA	
Picture of System Map	job_print.pdf
Picture of Dig Ticket	
System Map Title Block	
Image upload 1	Employee_Statement.pdf
Description of Image 1	Employee Statement
Image upload 2	20230131_1113391.jpg
Description of Image 2	Photo Damage
Image upload 3	Overview.jpg
Description of Image 3	Overview
Image upload 4	street_view.jpg
Description of Image 4	street view

Form Summary Image upload 5 **Description of Image 5** Image upload 6 **Description of Image 6** Image upload 7 **Description of Image 7** Image upload 8 **Description of Image 8 Incident Reported By:** Dan Cooper Job Title: Safety Specialist **Email address:** dcooper@veritacorp.com Phone number 616-250-7006 01/31/2023 Date: Signature:

The message has been sent from 47.50.98.142 us at 2023-02-01 on Chrome 109.0.0.0

Entry ID: 13

Referrer: (no referrer)

Form Host: https://www.veritanet.com/safety