



INCIDENT/INJURY REPORT

Incident Type:*

Verità Location*

Incident Date:*

Time of Incident:*

Date Reported:*

Incident Without... ▾

Northville ▾

01/30/2023



05:07 PM



01/31/2023



EMPLOYEE INFORMATION

Employee Name:*

Employee Phone Number:*

Mauricio

Gonzalez

313 799 8817

Employee Address:

3544 Wall Ave

Allen Park

Michigan ▾

48101

Employee Email Address:

mgluna048@gmail.com

Job Title:*

Laborer

Date of Hire:

04/04/2022



INCIDENT DETAILS

Crew Size:

Crew Foreman/Supervisor:*

4

Morrell

Graves

Incident Location:*

Niagara Parkway

Niagara Falls

State ▾

Location on Google map



Description of Incident: *Please describe in detail what happened**

Mauricio and Javiar were in a 3 foot pit adjusting an Everstream vault trying to get it level when Morrell pushed a pile of dirt into the pit on the side Mauricio was on. Mauricio had his back to Morrell at the time it happened. A big chunk of frozen dirt and sand approximately 16" x 10" broke off from the pile and struck Mauricio in his right calf muscle causing extreme pain and discomfort.

Describe any Unsafe Procedures or Equipment Failures which may have Contributed to the Incident:*

Morrell shouldn't have been pushing dirt into a pit with two employees inside of it.

What Has/Will be done to Prevent Similar Incidents from Occuring?*

Do not backfill holes with employees inside

ADDITIONAL PHOTOS AND DOCUMENTS

File / Image upload

78B58E... (2.6 MB)



File / Image upload

66A951... (2.6 MB)



File / Image upload

757E71... (4.6 MB)



File / Image upload

Choose files or drag here

File / Image upload

Choose files or drag here

File / Image upload

Choose files or drag here

File / Image upload

Choose files or drag here

File / Image upload

Choose files or drag here

SUBMISSION

Report Completed By:*

Jason

Job Title:*

Riley

Safety Specialist

Phone number:*

734 286 4177

Email address:*

jriley@veritacorp.com

Signature:*

Date:*

 Sign here  

01/31/2023 