

**Incident Detail**

|  |  |  |  |
|--|--|--|--|
| <b>Incident Name:</b> Verita truck 7500 drivers side window shattered          |  | <b>Date of Incident:</b> 01/23/2023 08:37 AM   |  |
| <b>Incident Type:</b> PROPERTY DAMAGE  |  |  |  |
| <b>Workday Period:</b> During normal work activities                           |  | <b>Activity Details:</b><br>After fueling the truck Shawn got into the drivers seat and before he closed the drivers side door the window shattered. It's a 2000 GMC 7500. |  |
| <b>Location:</b> Northville - She'll gas station Beck Rd & 5 Mile Rd, Plymouth |  |  |  |
| <b>At Fault Utility Strike? :</b><br>N/A                                       |  | <b>Was JSA posted and properly filled out?:</b><br>N/A   |  |
| <b>Hit-kit pictures included?:</b><br>N/A                                      |  | <b>Was employee sent for a drug/alcohol screen?:</b><br>No   |  |
| <b>Utility Locate #?:</b><br>N/A   |  | <b>Verita or Subcontractor Crew?:</b><br>Verita  |  |
| <b>If Subcontractor, please specify name::</b><br>N/A                          |  |  |  |

**Detail****Status**

Report Only (No Claim Filed)

**Type**

- Building (Exterior)       Building (Interior)  
 Equipment (Production)    Equipment (Non-Production)  
 Landscaping                 Merchandise/Inventory  
 Vehicle (Passenger)       Vehicle (Other)  
 Other

**Describe Incident (how, where, why)**

After fueling the truck Shawn got into the drivers seat and before he closed the drivers side door the window shattered. This didn't happen from opening or shutting the door. Do not understand how this happened, possibly something inside the door caused this to happen.

**Describe Extent of damage/loss**

Drivers side door window shattered. Completely gone.

**Person Information**

| Name           | Phone      | Email                | Address        | City | State | Zip   |
|----------------|------------|----------------------|----------------|------|-------|-------|
| Shawn mcnichol | 7347564233 | smcnichol@verita.com | 10454 varna st | Clio | Mi    | 48420 |

**Witness Information**

| Name           | Phone      | Email                | Address        | City | State | Zip   |
|----------------|------------|----------------------|----------------|------|-------|-------|
| Shawn mcnichol | 7347564233 | smcnichol@verita.com | 10454 varna st | Clio | Mi    | 48420 |

**Submission Detail****Submitted by:** Jason Riley**Date/Time:** 01/23/2023 07:40 AM**Doc ID:** #10676

Was filling truck with diesel at shell, 5 mile and beck rd. After refueling,loped the drivers door to enter the vehicle,as I stepped up on the first step the drivers window shattered.

A handwritten signature in black ink, appearing to read "S. McNichol". The signature is written in a cursive style with a large initial 'S' and a long, sweeping underline.

Incident Photo(s)

